



# TEXTURED COATING REMOVAL TRAINING

The Control of Asbestos Regulations 2012, paragraph 386, states that *...a full enclosure should be used for large-scale work (eg on textured coatings or artex)...where a full enclosure is used for non-licensable work, air extraction airflow rates as specified for licensable work should be used.* Large Scale work is defined as any area greater the 1m<sup>2</sup> in area.

This additional requirement ensures the spread of asbestos, when textured coating is removed. The non-licensable works with ACM's training course is carried out in accordance with HSG 210 – Asbestos Essentials, which limits the delegates to removing up to 1m<sup>2</sup>. This course is designed to provide the practical skills for employees to correctly set up the site to facilitate removing larger areas of textured coating. This course does involve practical hands on training with textured coating.

**A pre-requisite for attending this training course would be to have completed the non-licensed works with ACM's course within the past 3 months.**

*The following is a list of subjects that will be covered in the 1 day follow-on training session in Textured Coating Removal (this course DOES not include asbestos awareness):*

- **Control of Asbestos Regulations requirements on textured coating removal;**
- **Defining NNLW, Medical Requirements etc;**
- **Air Movement and Negative Pressure Unit;**
- **Practical Airlock Construction;**
- **Practical Enclosure Construction;**
- **Practical Textured Coating Removal;**
- **Practical Decontamination;**

The course can ONLY be held at our dedicated practical centre; the maximum number of delegates we recommend is 6 per session.

**Course timings are as follows:**

9:00 am – 4.00 pm approx

**On completion the successful delegate will be awarded the  
“Textured Coating Practical Removal Certificate”**

**To book this course please call:**

**0800 612 4115**

**[www.asbestostraininglimited.com](http://www.asbestostraininglimited.com)**